

RoHS Compliant




No.E-9158S

## Precision Parallel Blocks 4 Pairs Sets

- The 4 faces excluding the end face have a ground finish, which are machined in pairs.
- S50C is hardened to HRC46 to 53, and offers high wear resistance.
- Comes in a durable wood storage case.
- Individual pieces are also available for sale.

By using high precision parallel blocks with high parallelism, you can perform precision machining while preventing lift-up of workpieces.





## Specifications


| Order No. | No.       | Content of Set  |   | Weight (kg) |  |
|-----------|-----------|---|---|-------------|--|
| 934597    | HPA100SET | 8×15×100(HP27),10×20×100(HP28)<br>10×25×100(HP29),15×35×100(HP30)                     | Contains 4 types of 2 pieces of each in the box | 1.7         |  |
| 934598    | HPA125SET | 8×15×125(HP31),10×20×125(HP32)<br>10×30×125(HP33),15×40×125(HP34)                     | Contains 4 types of 2 pieces of each            | 2.4         |  |
| 901278    | HPA150SET | 15×20×150(HP2),15×30×150(HP3)<br>20×30×150(HP4),25×50×150(HP5)                        | Contains 4 types of 2 pieces of each            | 6.8         |  |
| 900097    | HPA200SET | 10×20×200(HP22),15×20×200(HP23)<br>15×30×200(HP24),20×30×200(HP25)<br>25×50×200(HP26) | Contains 5 types<br>of 2 pieces of<br>each      | 9.8         |  |


Useful for machining of the top surfaces of thin plates in particular.


tool with the vise.


◆For top surface machining ◆For machining through holes ◆For setting-up small pieces ◆For preventing damage to the vise Prevents interference of the cutting Useful for setting-up vises with a groove in the center.

Prevents damage to the vise by falling workpieces.









## Reference Pages



Jig Set-up Systems (Q-lock) Base Elements Clamp Units Clamping Parts Mechanical Parts

Surface Plates and Measurement Instruments

Index